



Western Michigan University
ScholarWorks at WMU

Legacy Scout Tickets from Pure Oil Company

8-20-2021

MGRRE_PureOilScoutTickets_Lincoln National Life Insurance Company_1_21117057360000

MGRRE

Western Michigan University

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

WMU ScholarWorks Citation

MGRRE, "MGRRE_PureOilScoutTickets_Lincoln National Life Insurance Company_1_21117057360000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 6635.
<https://scholarworks.wmich.edu/pure/6635>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



**MGRRE_PureOilScoutTickets_Lincoln National Life Insurance
Company_1_21117057360000**

API 21117057360000

Permit Number 5736

Lease Name Lincoln National Life Insurance Company

Well Number 1

County Montcalm

Township 12N

Range 05W

Section 29

2021 DEQ or Pure co_name Whitehead. R. A.

Pure Number 544

Latitude 43.40279

Longitude -84.94255

THE PURE OIL COMPANY
COMPLETION RECORD OF WELLS DRILLED BY OTHER OPERATORS
LOCATION REPORT

DATE December 29, 1938

No. 544

STATE Michigan COUNTY Montcalm DIST. Richland SEC. 29 TOWN 12 N RANGE 5 W
WELL No. 1 (SERIAL No. 544) FARM Lincoln Life Insurance Co. ACRES

NAME OF STREAM OR WATERS _____ QUADRANGLE C SW NW

OPERATOR R. A. Whitehead Map Richland Township, Montcalm County

R. A. Whitehead.
Feet from North Line of Farm

660 660 " " East " " "
660 660 " " South " " "
660 660 " " West " " "

Feet from North Line of Section

660 660 " " East " " "
660 660 " " South " " "
660 660 " " West " " "

○ LOCATION

① RIG

⊕ DRILLING

☀ GAS WELL

● OIL WELL

⬮ SMALL OIL WELL

LEGEND

⊙ DRY HOLE

⬮ DRY SHOWING OIL


⊙ DRY SHOWING GAS

⊙ ABANDONED LOCATION

☀ ABANDONED GAS WELL

⬮ ABANDONED OIL WELL

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location.



REMARKS:

SIGNED

Superintendent or Foreman.

Signed D. C. Shackelford